Insured/Applicant Name:	Application / Policy #:					
Address Inspected:	Address Inspected:					
Actual Year Built: Date Inspected:						
Minimum Photo Requirements: Dwelling: Each side Roof: Each slope Plumbing: Water heater, under cabinet plumbing/drains, exposed valves Main electrical service panel with interior door label Electrical box with panel off All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.						
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.						
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.						
Main Panel Type: ☐ Circuit breaker ☐ Fuse Total Amps: Is amperage sufficient for current usage? ☐ Yes ☐ No (explain)		Second Panel Type: Circuit breaker Fuse Total Amps: Is amperage sufficient for current usage? Yes No (explain)				
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repaired via COPALUM crimp Connections repaired via AlumiConn						
Hazards Present Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing		☐ Double taps ☐ Exposed wiring ☐ Unsafe wiring ☐ Improper breaker size ☐ Scorching ☐ Other (explain)				
General condition of the electrical system: Satisfactory Unsatisfactory (explain)						
Supplemental information						
Main Panel Panel age: Year last updated: Brand/Model:	Second Panel Panel age: Year last updated: Brand/Model:		Wiring Type ☐ Copper ☐ MN, BX or Conduit			

HVAC System					
Central AC:					
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed?					
Supplemental Information					
Age of system: Year last updated: (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Discording Constant					
Plumbing System Is there a temperature pressure relief valve on the water heater? ☐ Yes ☐ No Is there any indication of an active leak? ☐ Yes ☐ No Is there any indication of a prior leak? ☐ Yes ☐ No Water heater location:					
General condition of the following plumbing fixtures and connections	s to appliances:				
Satisfactory Unsatisfactory N/A Dishwasher	Satisfactory Unsatisfactory N/A Toilets				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System: Original to home Completely re-piped Partially re-piped (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply) Copper PVC/CPVC Galvanized PEX Polybutylene Other (specify)				

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)					
Predominant Roof		Secondary Roof	Secondary Roof		
Covering material:		Covering material:	Covering material:		
Roof age (years):		Roof age (years):	Roof age (years):		
Remaining useful life (years):		Remaining useful life (years):	Remaining useful life (years):		
Date of last roofing permit:	Date of last roofing permit:		Date of last roofing permit:		
Date of last update:		Date of last update:	Date of last update:		
If updated (check one):		If updated (check one):	If updated (check one):		
☐ Full replacement		☐ Full replacement	☐ Full replacement		
☐ Partial replacement		☐ Partial replacement	☐ Partial replacement		
% of replacement:		% of replacement:	% of replacement:		
Overall condition:		Overall condition:	Overall condition:		
☐ Satisfactory		☐ Satisfactory	☐ Satisfactory		
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)	☐ Unsatisfactory (explain below)		
Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Interior ceilings Yes No		(check all that apply and explain bel Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or Soft spots in decking Visible hail damage Any visible signs of leaks?	□ Cupping/curling □ Excessive granule loss □ Exposed asphalt □ Exposed felt □ Missing/loose/cracked tabs or tiles □ Soft spots in decking □ Visible hail damage Any visible signs of leaks? □ Yes □ No Attic/underside of decking □ Yes □ No		
Additional Comments/Observations (use additional pages if needed):					
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.					
Inspector Signature	Title	License Number	Date		
Company Name	License Type	Work Phone	_		

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.